

FIG. 1

i. i



.,1

F1G. 2







FIG. 4



F1G. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10

Sept. Offi





FIG. 11






FIG. 13




FIG. 14









FIG. 15











, 1

F1G. 20

					,		
(84:mm:ss)	TIME AT WHICH ID ERROR HAS OCCURRED				01:32:13		
	RECOVERY IDENTIFICATION HAS BEEN IMPOSSIBLE	32:32	12:80:00	00:27:46			
	TIME OF RECOVERY	03:14:28	04:01:00	14:25:46			
	TIME OF DISAPPEARANCE	02:38:56	03:52:39	13:58:00			
	KEY WHICH THE KEY IS IN WITHDRAWAL TIME INSERTED STATE					00:35:20	
						03:14:05	
	KEY INSERTION TIME					02:37:45	
	KIND	MAIN BODY FRAME	MAIN BODY FRAME	GLASS FRAME	GLASS FRAME	KEY	
	MACHINE	NO. 0002	NO. 0002	NO. 0134	NO. 0063	NO. 0002	
DATE:	ID CODE	0583208098	0583208098	0296738591	1368207964	9265380711	